

FIG.1 (Prior Art)




(b) Example of display suitable for slow measuring periods

(a) Example of display suitable for fast measuring periods




3/9



4/9

FIG.4







FIG.5

6/9

FIG.6







FIG.8






FIG.5